



SEPTIC TANK EXISTS

CONNECT TO EXISTING SEPTIC TANK  
MAY REQUIRE GREASE TRAP

EXTENSION UNDER EXISTING VERANDAH

MODIFY EXISTING RET WALL