
# **APPENDIX 5**

## **ATTACHMENT 1**






FLOOR PLAN SCALE 1:100




REV	DATE:	REMARKS:	REV	DATE:	REMARKS:	DRAWING TITLE:	PROJECT:
А	02.10.13	DRAWING CURRENT AS OF TODAY	E			FLOOR PLAN	-
В			F				
С			G				
D			Н				
		PROPERTY OF "THE CITY OF JOONDALUP BUILDING ASSET MANA IS BEFORE FABRICATION AND AGAINST ON SITE DIMENSIONS	THIS DRAWING TO BE PLOTTED ON A2 SIZE PAPER - DO NOT SCALE, IF IN DOUBT ENQUIRE WITH ASSET MGT 94004340	46 WARWICK			

LEASED AREA 766.90 m<sup>2</sup>



### **ATTACHMENT 3**




## **OPINION OF PROBABLE COST**

#### PROJECT: COJ Sorrento Tennis Club

#### Itemised costs

Item	Description		Rate	Total
	ITEMISED COSTS			
	All items include Contingencies, Professional fees and building cost escalation up to June 2017			
1	Bar refurbishment			135,000
2	Players Area and Foyer refurbishment			85,000
3	Bi-fold external doors at Players Area			74,000
4	New internal storeroom			14,000
5	Toilet/changeroom refurbishment			39,000
6	Replacement of paving and drainage systems around building			62,000
7	New ramp and paving to main entrance (east side of building)			47,000
8	Temporary facilities			48,000
				<u>504,000</u>



# City of Joondalup


90 Boas Ave, Joondalup WA 6027 PO Box 21, Joondalup WA 6919 Ph: 08 9400 4000 Fax: 08 9300 1383 info@joondalup.wa.gov.au www.joondalup.wa.gov.au


# Scale(A4):1:564

## Date: 22/05/2015

DISCLAIMER: While every care is taken to ensure the accuracy of this data, the City of Joondalup makes no representations or warranties about its accuracy, completeness or suitability for any particular purpose and disclaims all liability for all expenses, losses, damages and costs which you might incur as a result of the data being inaccurate or incomplete in any way and for any reason.

# Sorrento Football (soccer) Clubroom






#### SCOPE OF WORKS:

- 1 REPAINT ALL WALLS, DOORS AND FRAMES IN AREAS BEING WORKED ON AS REPAINT ALL WALLS, DOORS AND FRANKES IN AREAS BEING WORKED ON AS PER COL SPECES. RE-TILE KITCHEN AS SPECIFIED. CLEAN ALL TILES IN CHANGE ROOMS, TOILETS & SHOWERS, REPLACE ANY DAMAGED TILES, TO MATCH EXISTING IN AREAS BEING WORKED ON. (INCLUDING AREAS SHOWN HATCHED)

- MAKE GOOD ALL SURFACES.
- INVESTIGATE AND ASSESS FLECTRICAL WORK MAKE TO A S WHERE REGUIRED



## **OPINION OF PROBABLE COST**

#### PROJECT: COJ Sorrento Soccer Club

Item	Description		Rate	Total
	ITEMISED COSTS			
	All items include Contingencies, Professional fees and building cost escalation up to June 2017			
1	Internal toilet refurbishment			97,000
2	Main hall refurbishment			75,000
3	Bifold doors to Clubroom			27,000
4	Verandah extension			59,000
5	Kitchen/bar refurbishment			52,000
6	Changeroom refurbishment			22,000
7	Replacement of evaporative cooling to hall			39,000
8	New car parking and disabled bays			29,000
9	Electrical investigation			23,000
10	New store north of existing building			105,000
11	New store and UAT			54,000
12	Temporary facilities			40,000
				<u>622,000</u>